

3H Equine Rehabilitation Stable

3H Equine Rehabilitation Stable

New Hill, North Carolina



- 1 Rehabilitation Stable
- 2 Pasture
- 3 Clients Home
- 4 Admin
- 5 Competition Track
- 6 Stalls
- 7 Covered Storage



Existing Site Conditions

The 3H Equine Rehabilitation Stable is an adaptive-reuse of our clients former veterinary clinic. A fire caused from hay chaff build up and inadequate air circulation, left only ground level concrete walls. It became imperative for our client and the design team to memorialize the history of the clinic through the reclamation of these walls in the new facility.




2021



intervention





ventilation



geometry








geometry

- 1 Stalls
- 2 Treatment/ Wash Bay
- 3 Tack Room
- 4 Toilet
- 5 Laundry
- 6 Feed
- 7 Storage
- 8 Ship Ladder (Access to Loft)
- 9 Aisle
- 10 Covered Workspace




Organization and Program

The timber intervention straddles the existing walls and is organized around the proportions of a horse stall. The regular grid of columns creates a central aisle accommodating safe movement animals and their handlers and ties into broader campus paths.










ventilation

stalls

aisle


stalls

covered workspace



0 5 10

Section | Stalls and Covered Workspace



49791898



Functionality

Cantilevered eaves on the east elevation provide shade for working stable hands and clearance access for farrier trucks.



Program

Stalls, treatment/wash bays, and tack rooms line the central aisle, offering framed views of the site.

2024



2021



